

PLANT INSPECTION COMMITTEES REPORTS

JANUARY 4 & 6, 1936

INSIDE INSPECTION BY J. J. GREGORY AND JAMES NUNLEY:

1. Switch lights at Supply entry in Section 2 of No. 1 Mine were not operating.
2. Visited drill crew and slate shovel crew in Section 10 B-seam tunnel. Drill crew was using water while drilling.
3. Inspected all wire and bonding for shooting rock tunnel which was well bonded and soldered.
4. Visited two drill crews, slate shovel crew, seven trackmen and two bratticemen in 3rd right face entry of Section 9. Drills were not in operation at the time of inspection. All men were working safely.
5. Signal lights were not operating for trips coming out of Section 10 on No. 2 main.
6. No coal found in slate dump.
7. Needs general cleaning up at slate bin where slate larry is being loaded.
8. No. 1 Mine fan in good condition.
9. All mine buildings were found in good condition except sand house.
10. Steps at No. 1 upper tipple in need of repairs.
11. Steps at No. 1 lower tipple in need of repairs.

OUTSIDE INSPECTION BY W. S. PALMER AND WILLIAM GLADSON:

1. Two tubs of trash in furnace room at White School. Also axe and shovel with bad handles.
2. Hand rails along stairway leading from west side of stage to basement of school building are loose.
3. Linoleum in dish room and kitchen of Hotel in bad condition--tripping hazard.
4. Visited all other public and operating buildings and found them in good condition.
5. The general condition of the town was very good.