

Operating Schedule for Week ending		Jan. 5, 1946					
	Weekly re- quirements	31 Mon.	1 Tues.	2 Wed.	3 Thurs.	4 Fri.	5 Sat.
5" Screenings							
3" Screenings							
<b>Peabody</b>	<b>322</b>	<b>52</b>	<b>53</b>	<b>51</b>	<b>52</b>	<b>56</b>	<b>58</b>
Mine Run							
<b>Steel Mill</b>	<b>12631</b>	<b>1624</b>	<b>2137</b>	<b>2135</b>	<b>2164</b>	<b>2516</b>	<b>2055</b>
Lake Shipments							
5" Block							
<b>Peabody</b>	<b>3599</b>	<b>520</b>	<b>569</b>	<b>682</b>	<b>527</b>	<b>698</b>	<b>603</b>
<b>Domestic</b>	<b>373</b>	<b>46</b>	<b>47</b>	<b>95</b>	<b>46</b>	<b>94</b>	<b>45</b>
5x3 Egg							
Total Shipments	<b>16552</b>	<b>2196</b>	<b>2759</b>	<b>2868</b>	<b>2743</b>	<b>3270</b>	<b>2716</b>
Production		<b>2456</b>	<b>2852</b>	<b>3078</b>	<b>3022</b>	<b>3113</b>	<b>2751</b>
Avg. daily prod.		<b>2480</b>	<b>2852</b>	<b>2965</b>	<b>2984</b>	<b>3017</b>	<b>2964</b>
On Hand							
Mine Run X		-	-	-	-	-	-
" F		-	-	-	-	-	-
Block		-	-	-	-	-	-
Egg		-	-	-	-	-	-
Domestic		<b>2</b>	<b>3</b>	<b>1</b>	<b>3</b>	<b>2</b>	<b>3</b>