

PLANT INSPECTION COMMITTEES FOR THE YEAR 1938

No. 1 MINE INSPECTIONS:

January 24th.
J. E. Raines
E. L. Bradberry

February 15th.
Ambrose Jarvis
H. C. Hensley

March 10th.
J. D. Stansbury
Chester Poff

April 20th.
E. K. Newman
Gordon Gilley

May 20th.
Marion McCarty
Floyd Kirk

June 23rd.
S. H. Hightower
Mont Rasnick

July 21st.
M. N. Huddleston
Jack Patton

August 11th.
Arthur Kilgore
Henry Walters

September 22nd.
W. S. Palmer
Matt Fields

October 13th.
T. H. Luke
Raymond Grogan

November 17th.
A. J. McCarty
A. J. Fawbush

December 14th.
F. C. Cole
Ben F. Davis

GENERAL OUTSIDE INSPECTIONS:

January 14th.
D. W. Vittum
John L. Shepherd

February 8th.
J. W. Nichols
O. T. Cannon

March 11th.
Otis Helton
S. E. Warren

April 19th.
J. S. Burns
Paul Vaughn

May 16th.
W. H. Boatright
Herbert Jackson

June 21st.
W. S. Palmer
Paul White

July 18th.
J. J. Gregory
James Estep

August 4th.
C. L. Griggs
Homer M. Hardin

August 31st.
H. G. Stubblefield
Lawrence Hensley

October 18th.
W. R. Shepherd
H. V. Buchanan

November 15th.
E. D. Sturgill
L. H. Tucker

December 16th.
D. L. Nunnery
C. C. Compton