

Manhole Cover Corrections

7/24/42

- ~~Rear of and above Ho. 142 - make hand holes smaller~~
~~Opp. House 154 - " " "~~
~~Between Ho. 157 & 159 in road - " " "~~
~~South of Ho. 180 - " " "~~
~~Opp. House 166 - raise 12" Completed~~
~~" Foreign Boarding Ho kitchen - raise 6" "~~
~~Opp. Ho. 164 - raise 8" - provide cover that fits "~~
~~Rear Ho. 49 - raise 12" "~~
~~Above Ho. 69 in road - make hand holes smaller~~
~~Near Ho. 206 - raise 12" "~~
~~" " 209 - " 6" "~~
~~" " 215 - " 6" "~~

~~Footer under north abutment for sewer crossing near colored church bad condition - footer should be carried deeper~~

~~Between houses 230 & 232 on opp. side of street on hillside - raise 36"~~

~~Footers under abutments of sewer crossing between houses 232 & 234 - bad condition - should be raised deeper~~