

FACTORY INSURANCE ASSOCIATION  
WESTERN REGIONAL OFFICE  
CHICAGO 4, ILLINOIS

COPY

PROSPECT

MARCH 29, 1958

INLAND STEEL COMPANY, INC.  
WHEELWRIGHT & PRICE, KENTUCKY

RECOMMENDATIONS

From inspection by our Mr. W. F. Schacht.

WHEELWRIGHT, KENTUCKY - ABOVE GROUND

58-1. Install automatic sprinklers in the following locations:

- (a) In basement section of Club House in Bowling Alley.  
*(Interior ceiling and walls are of highly combustible material.)*
- (b) In all sections as well as roof ceiling space of Main Office Building.
- (c) In Store No. 1 in basement area.  
*(Merchandise consists principally of upholstered furniture, highly combustible.)*
- (d) In Ready To Wear Store area of Club House.
- (e) In Warehouse at rear of No. 1 store.  
*(Storage of highly combustible merchandise consisting of upholstered furniture.)*
- (f) In Telephone Exchange. *elect. goods, etc.*
- (g) In Theater Building.
- (h) In Community Building.
- (i) In Bath House.

58-2. Recorded portable watch service should be provided hourly nights, idle days and holidays in the following locations: Club House basement and Bowling Alley, all floors of Main Office Building, Telephone Exchange, Ready To Wear Store in Club House, both floors of Store No. 1, Warehouse at rear of Store No. 1, Theater Building, Community Building, Bath House, Maintenance Shop, Laundry, Store No. 2, Colored Pool Room, Shoe & T. V. Repair Building, Service Station, unattended buildings at Wheelwright Portal.