

17

ACCIDENT
DEATH TOLL

- Working under loose top
- No safety posts set.
- Running motor wild.
- Riding front bumpers.
- Cutting unsafe working places. Loose cable and clothes.
- Running motors too close together.
- Knocked out of Motor. Taking chances. Etc. Etc.
- Fall between cars Etc. etc.

