(✓ Roland
or Hercules
Hag. Data Sheet.)

Pelvine Calf
① no operator



how many people do this everything

role (operator was brother of his engine)

degree of danger in clothing
polyester
cotton
cotton fire retard

② H.P. cotton polyester 60%

F.S. Pulpit operated
act. bonding of a turning agitator
(grease oil barrier)



for tank cleaning
use of Nomex type
surgical dining gloves
high neck
& long sleeves

for protection of hierarchy
people
fire blankets
working together
(the rain rx.)

SW
③ pressure cleaning / solvent a 500 g tank

(in an enclosed pipe
transfer flow by <1.5'/sec)

ground-bond holes here. by a maint dept modification of existing equip.





see fire on roof thru seat

OSHA - annual retraining on holding hazy matl.

Ferro
④ Epoxy Oils PVC linked



adding a
fiberdrum of
antioxidant
Santicoat - phenol - sulfonamide
3' rope spare a dehydrated sulfide
when added.

other possible source
rubber boots - cloth gloves
developed chg going up & down stairs
he took gloves off & was holding the
the inclinated spark at the edge.

the metal rim of drum & when touched
aerosol going out of the
another case
where operator did it was
shower
it was right around to the
he went to wear rain to
take his clothes off
did it want to get wet
polyester - cot clothes

was pumping an empty drum into the while adding power
foamed a aerosol & lead to a dust explosion as he poured power in.