

34+55 End
 32+30 PC 10° C
 30+40 PT
 HB 29+66 10° C
 HB 28+76
 HB 27+99

Tipple 25+29

HB 23+53
 HB 22+68
 23+42 PT
 9° C.R.
 20+30 PC

19+31 HB



12+107 PC
 12° C
 10+36 PC

9+59 PT

12° C

1+00 PC
 HB=0.0

Main Line L & E
 Passing Tracks

To Jackson →

To Morehead's →

HAZARD DEAN COAL CO. TRACKS
 Hazard, Ky. As Constructed
 office of Asst. Engr.
 Scale 1" = 200'
 Lex. Ky.
 Feb. 11, '15
 M 5433-Con.